

COMMENTS & OBSERVATIONS ON "LOCKDOWN" PHOTO

WEEK 1

1. All my recent photos of ICR's show part or all of the end casing around the coupling removed. Is that a general change that has occurred since 2013 and is there a reason for it - damage in service, easier access for maintenance?
Tim Morton